ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli

Street ID	Street Name	Significant Landmark
W0630, W0634, W0699, W0703, W0701	NA	Pappanna Badavane near GR Kalyana Mantapa

Segment No.	Total Length (m)
8/C-W0630/S013621	364.11

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	142.50	77.579109	13.047687	77.579635	13.048867	M0021	W0632
2	75.32	77.578740	13.047796	77.578958	13.048442	M0021	W0634
3	146.29	77.578381	13.047868	77.578708	13.049148	M0021	W0630

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drain at Pappanna Badavane near GR Kalyana Mantapa in ward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	2500000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements to Roads and Drain at Pappanna Badavane near GR Kalyana Mantapa in ward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-16-000009

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/215/2015-16	16/02/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
16/02/2016	15/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.NARASIMHA RAJU		0.00

Phone No.	E-Mail ID
9448083246	

Field Inspection Details

Number of Trees	Any Other Information	Name
4		Srinivasa Murthy
Date of Inspection	**Remarks**	
26/07/2016	completed	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0630, W0634, W0699, W0703,

Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/07/2016	25/08/2016	COMPLETED
SE	VASU K M	26/07/2016	25/08/2016	COMPLETED
EE	YARAPPA REDDY	26/07/2016	25/08/2016	COMPLETED
AEE	SHIVAKUMAR	26/07/2016	25/08/2016	COMPLETED
AE	SRINIVASA MURTHY	26/07/2016	25/08/2016	COMPLETED
AE	SRINIVASA MURTHY	26/07/2016	25/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0630, W0634, W0699, W0703,